

Office of Facilities

“Smarta” Public Restrooms

Lindbergh Pilot



Current State




- Lack of vandal resistant fixtures:

- Surface Mount Fixtures
- Leverage Fixtures
- Free-flowing Supplies

- Lack of access control other than by onsite Marta personnel

- Lack of loitering control other than by onsite Marta personnel




Restroom Smartening



- Loitering Control-Timed Usage with smart motion sensors
- Two Way external communication with video monitoring
- Manned & Monitored Access Control through PFS call center
- Two Way emergency internal audial communication



Restroom Toughening



- Vandal resistant fixtures
- Break/Chip resistant fixtures
- Flush/Surface Mount Fixtures
- Metered Supplies
- Touch-free sensors